TOPS Working Committee
Project Update
May 5, 2021
Emily Duncan and David Deitemeyer





Rock Island Pond 1 Project




- Correction of over 1.5 acres of encroachment
- Remove invasive vegetation
- Reduce erosion and improve drainage
- Water Quality and Retention
- Channel and Slope Stabilization
- Reduce rogue trails in open space









- Over a ½ mile of Multi-Use Trail
- Access from Broken Circle Road
- Directs trail users around stormwater facility
- New TOPS Open Space Wayfinding Installed Spring 2021
- Ongoing Stormwater projects to address erosion





 New TOPS Open Space Wayfinding Installed Spring 2021





